



**TRIAX 2000 / TRIAX 2010 / TRIAX 2015 NON-WARRANTEE REPAIRS
PRICE SCHEDULE
February 19, 2016
ALL PRICES IN US DOLLARS**

CABLES AND CONNECTIONS (Service Code CC):

1. New Cables, 16' long – 3 or 4 conductor	185.00 each
2. New Cable, 16' long – 7 conductor	225.00 each
3. Extra cable length	3.25 / foot
4. Replace cable, reuse plugs	120.00 each
5. Replace cable plug, 3 or 4 conductor	60.00 each
6. Spare plug, not installed, 3 or 4 conductor	50.00 each
7. Spare plug, not installed, 7 conductor	70.00 each
8. Replace receptacle, 3 or 4 conductor	75.00 each
9. Replace receptacle, 7 conductor	100.00 each
10. Rewire plug or receptacle – reuse all parts	45.00 each
11. Spare receptacle, not installed	50.00 each
12. New cable, 4' long 4 conductor (for A missile)	165.00 each
13. New cable, 4' long 7 conductor (for A missile)	200.00 each

HAND HELD (Service Code HH):

1. Replace keypad	150.00
2. Plug in battery box	30.00
3. Battery box receptacle	40.00
4. Replacement hand held (Triax 2010)	3750.00
5. Replacement hand held (Triax 2015)	3000.00

TRIPOD (Service Code TR):

1. Replace steel lift cable	145.00
2. Replace magnet	420.00
3. Upgrade lift cable clamp	435.00
4. Replace black coiled cable	175.00
5. Replacement leg section – screw type	165.00 each
6. Replacement leg section – snap together	230.00 each
7. Replace aluminum lid	105.00
8. Circuit board repair – any	125.00
9. Replacement tripod (with full leg set)	4250.00



10. Replace battery holder	100.00
11. Snap together leg set (include carrying bag)	2185.00
12. Leg carrying bag	200.00

HEAD FORM (Service Code HF):

1. Replacement accelerometer (Includes system calibration)	1600.00
2. Accelerometer cable (reuse receptacle)	110.00
3. Accelerometer cable with new receptacle	195.00
4. Replacement head form (complete – Triax 2000)	2875.00
5. Replacement head form (complete – Triax 2010)	3500.00
6. Replacement head form (complete – Triax 2015)	4250.00

SYSTEM (Service Code SY):

1. Calibration (A missile or Tripod)	825.00
2. Calibration (A missile and Tripod, 1 handheld)	1325.00
3. Calibration rush charge (1 week, check availability)	300.00

NOTE: During calibration the accelerometer might be noted as having drifted beyond nominal tolerances. Depending on the magnitude of this drift the customer may be offered the opportunity to proceed with the existing sensor with applicable note on the certificate. If the sensor has drifted beyond usable range replacement (see head form #1) is required.

4. Reference pad	25.00
5. Padded hand held carrying case	50.00
6. Padded head form carrying case	50.00
7. Hard side golf bag	375.00
8. Desktop cradle with COM cable	175.00

HOURLY LABOR CHARGES (Service Code LB):

1. Repair or test work not otherwise listed (1 hour minimum)	120.00 / hour
---	---------------

TRIAx 2000 to TRIAX 2015 Upgrade



An existing Triax 2000 or Triax 2010 system can be upgraded to the Triax 2015 wireless standard. Include fresh calibration certificate. Does not include new tripod legs.

- | | |
|------------------------------------|---------|
| 1. Tripod E head form based system | 4500.00 |
| 2. Tube A missile based system | 5300.00 |

Before upgrade begins a full inspection of the existing system components is performed. If any parts are worn or damaged beyond re-use additional charges may apply. Customer will be notified before any work commences. Please see note about accelerometer drift in SYSTEM section above.

NOTE: The Triax 2000 has been replaced by the Triax 2015. Many of the Triax 2000 components are no longer available, and repairs to Triax 2000 systems are subject to parts on hand. Triax 2010 and Triax 2015 systems are fully supported.

LEAD TIME:

Normal lead time on any repair is (2) working days after we receive the items in our facilities. Please call before shipment to ensure availability of technician time.

Exceptions to the lead time can result from unavailability of repair parts or outside contract calibration services. Exceptions will be noted within (1) day of our receipt of the items. Expedited charges will not apply in exception cases.

SHIPPING:

Prices do not include return shipping charges. Return shipping will be by UPS ground unless otherwise specified and agreed to by customer. Shipping charges will be prepaid and added to invoice amount unless customer supplies their shipper account number and shipment instructions.

For customers outside the United States please be certain to mark the commercial invoice / shipping papers "Electronic Instrument – Made in USA – Return for repair." Failure to do so will result in import duties being assessed which will be the responsibility of the customer. Any import duties assessed for any reason are the responsibility of the customer and will be added to the repair charge total.



**alpha
automation**

alpha automation, inc.
125-127 Walters Avenue
Trenton, New Jersey 08638
609-882-0366 FAX 609-882-0382

PAYMENT TERMS:

All calibration, repair and shipment charges must be paid before return shipment is made. We accept checks, MasterCard, Visa and bank wire transfers.

WARRANTEE:

All repairs are covered by warrantee for (90) days after shipment from our facility. Customer is responsible for any charges to return items to our facility for warrantee service.

<< END >>